

DETAILED ACCIDENT REPORT (DAR)
ANNEXURE 'A'
MECHANICAL INSPECTION REPORT
 (Submit separate Mechanical Report for each vehicle)

2102
 1/12/2017

H.T.V. / M.G.V. / L.G.V.		
1	Case FIR No.	699/17
2	Under Section	v/s 279, 337, 338, 304(A)
3	Police Station	united police station
4	Registration No. of the Vehicle	MH-23/Y-1397
5	Make, Model Name, Colour & Type of Vehicle	make - Chevrolet model - Tavera colour - silver TYPE - LMV
6	In case of HTV/MGV/LGV (a) Whether Lateral Under Run Protective Device (LUPD) & Rear Under Run Protective Device (RUPD) installed? (For vehicle weighing 3.5 ton or more) (b) Whether speed governor installed & functional or otherwise?	} N/A.
7	In case of commercial vehicle: a) Particulars of fitness b) Particulars of permit	} N/A.
8	Point of impact and damage -	on side.
9	Mechanical condition of the vehicle -	m.v. found Not in Roadworthiness condition
10	Paint marks (if any) -	-
11	Condition of braking System i.e. working or not?	m.v. found Not in Roadworthy condition
12	Whether the vehicle fitted with Anti-lock Braking System (ABS)? a) If Yes, whether it is functioning or not? b) Whether trials regarding skid marks of ABS fitted vehicle have been carried out to estimate the speed of the vehicle	} N/A
13	Whether vehicle modified by a) Installing CNG/LPG Kit b) Change of vehicle body	} N/A
14	Condition of tyres-whether original or retreaded?	original - Rear side both tyres worn out.
15	Whether horn was installed and functional?	electric horn, functional
16	Whether the brake lights & other lights functional?	m.v. found Not in Roadworthiness condition
17	Condition of safety bags in the vehicle	N/A.

11632
 29/11/2017

18	Whether the vehicle properly maintained?	—
19	Whether the vehicle and faulty number plate?	NO
20	Whether the vehicle had tinted glasses?	NO
21	If the vehicle was educational institution bus, whether the vehicle was fitted with the doors that can be shut and whether the vehicle had a suitable inscription to indicate that they are in the duty of an educational institute, as per the guidelines laid down in MC Mehta v. Union of India, (1998) 1 SCC 676 and MC Mehta v. Union of India (1999) 1 SCC 413?	N/A
22	Details of damage on the vehicle - ① front side bonnet damaged & pressed inside. ② front side bumper damaged & Head light Assy. found broken & misplaced ③ windshield (front side) found broken & frame also found pressed inside & damaged ④ radiator damaged ⑤ left side panel & doors are damaged ⑥ top panel pressed inside ⑦ All doors are damaged ⑧ All seat reassembled & misplaced. ⑨ Right side tail lamp Assy. found missing ⑩ front door damaged. ⑪ M.R. found Not in Roadworthiness condition hence opinion can not be given	

Mitesh Digambar Chaudhari
24/11/17

Mechanical Officer
(Name & Stamp)
Mitesh Digambar Chaudhari
A.I.M.V. Dy. RTO Chamba
SHO
(Name & Stamp)

Date: 24/11/17.

