



23

DETAILED ACCIDENT REPORT (DAR)
ANNEXURE 'A'
MECHANICAL INSPECTION REPORT
(Submit separate Mechanical Report for each vehicle)

2103
1/12/2017

H.T.V. / M.G.V. / L.G.V.		
1	Case FIR No.	704/17
2	Under Section	v/s 279, 337, 338, 304(A)
3	Police Station	Ummed police station
4	Registration No. of the Vehicle	MH-04/DS-9177
5	Make, Model Name, Colour & Type of Vehicle	Make - TATA Model - 1613 colour - Brown Type - HGV
6	In case of HTV/MGV/LGV (a) Whether Lateral Under Run Protective Device (LUPD) & Rear Under Run Protective Device (RUPD) installed? (For vehicle weighing 3.5 ton or more) (b) Whether speed governor installed & functional or otherwise?	RUPD - fitted LUPD - Not fitted Not found at the time of inspection
7	In case of commercial vehicle: a) Particulars of fitness b) Particulars of permit	Not produced at the time of inspection
8	Point of impact and damage -	front right side
9	Mechanical condition of the vehicle -	m.v. found not in Roadworthiness condition
10	Paint marks (if any) -	-
11	Condition of braking System i.e. working or not?	m.v. found not in Roadworthiness cond.
12	Whether the vehicle fitted with Anti-lock Braking System (ABS)? a) If Yes, whether it is functioning or not? b) Whether trials regarding skid marks of ABS fitted vehicle have been carried out to estimate the speed of the vehicle	N/A
13	Whether vehicle modified by a) Installing CNG/LPG Kit b) Change of vehicle body	N/A
14	Condition of tyres-whether original or retreated ?	original - front right side wheel missing
15	Whether horn was installed and functional ?	functional
16	Whether the brake lights & other lights functional ?	m.v. found not in Roadworthiness cond.
17	Condition of safety bags in the vehicle	N/A

11631
29/11/2017

18	Whether the vehicle properly maintained ?	-
19	Whether the vehicle and faulty number plate?	NO
20	Whether the vehicle had tinted glasses?	NO
21	If the vehicle was educational institution bus, whether the vehicle was fitted with the doors that can be shut and whether the vehicle had a suitable inscription to indicate that they are in the duty of an educational institute, as per the guidelines laid down in MC Mehta v. Union of India, (1998) 1 SCC 676 and MC Mehta v. Union of India (1999) 1 SCC 413 ?	Yes
22	Details of damage on the vehicle - ① front Bumper damaged ② right side front windshield found broken. ③ front Axle Right side wheel found missing ④ Driver side door damaged. ⑤ Lead body damaged slightly. ⑥ m.v. found not in Road-worthy condition hence opinion can not be given	

(Signature)
24/11/17

Mechanical Officer
(Name & Stamp)

Neelish D. Chaudhari
A.E.M.V. Dy RTO Chandrapur
SHO
(Name & Stamp)

Date : 24/11/17

