19 Sec. ACCIDENT REPORT FORM Fatal 314.49. 23/17 337,358,304mIPC - REDOON 184 AMONI 47 95.247/2017, 16/02/17. edistered number of lorry axle weight should be Condition of brakes and brake connections Due to Front impact Condition of Steering, Steering arms and driver side body damage. connection and engine control Engine control damage Deiden seat allaps C Condition of gear box and differential Battery not found; steering wheel 'En its connections Frame (side; front & rear members) Frame, Wheels, axles found 7. Wheels, axles and springs (front and rear) inorder Any other defects worthy of special M. V. acco not in road woothy mention. condition. Hence M. v could not be road fested and opinion can not be given Was accident, in the opinion of the Examining Officer due to any mechanical defects in the vehicles? This opinion to be expressed in serious case only 10. Is Registration and Tax in order? no be varify by 2.0. 11. If a heavy motor vehicle is insurance in order? 12. If a transport vehicle, are the Certificate of Fitness and permit in order? Inward 10 48, 16/02/17 givat, +110]-Call received on 20/02/17; 16 40 hrs; Police Date, time and place of inspection Station Paeshioni Name of Driver .. Pobe varily by 2.0 M.D.L. No. Validity Inspector of Motor No. Forwarded with compliments to the P.I. for information and report on action taken.