ACCIDENT REPORT	KI FURM
olice Station	Passemi Police Station
ption and registered number of le (if a lorry, axle weight should be	mn:31 Tata Fruck w.8556 Tipper 16,200lgs
connections	Intact
4. Condition of Steering, Steering arms and connection and engine control	Steering Connection damaged.
5. Condition of gear box and differential	Intact
6. Frame (side; front & rear members)	Intact
7. Wheels, axles and springs (front and rear	Intact
8. Any other defects worthy of special	De Right hand side front Head lamp of damaged. @ Bonnet damaged
	on road. Hence opinion connect be
10. Is Registration and Tax in order?	
11. If a heavy motor vehicle is insurance in order?	Document were not available fer verification at the time of inspection
12. If a transport vehicle, are the Certificate of Fitness and permit in order?	of inspection
Call received on Date, time and place of inspection	4.3.17, 12:45 less, Posseou"
Name of Driver	11.2
M.D.L. No As per Validity F. Z.R.	1
Validity F. Z.R.	Inspector of Motor Vehicles, नि.
	of 20 प्रा.म.स्रो., नागपूर (ग्रापिण)
Forwarded with compliments to the P.T. Passeon's Palice Station.	