

## ANNEXURE 'A'

MECHANICAL INSPECTION REPORT (DAR)

F	नामप्र	071
1)	Case FIR No.	366   18
2)	Under Section	279, 337, 184 1040
3)	Police Station	P.S. RAMBEK
4)	Registration No. of the Vehicle	M440 K-7697
5)	Make, Model Name, Colour & Type of Vehicle	House CD DELAXE   Black 18m.
6)	In case of HTV/ MGV/LGV  (a) Whether Lateral Under Run Protective Device (LUPD) & Rear Under Run Protective Device (RUPD) installed? (For vehicle weighing 3.5 ton or more) (b) Whether speed governor installed & functional or otherwise?	HA
7)	In case of commercial vehicle:  (a) Particulars of fitness  (b) Particulars of permit	NA
8)	Point of impact and damage-	Front side
9)	Mechanical condition of the vehicle-	THORDER
10)	Paint marks (if any-)	_
11)	Condition of braking System i.e. working or not?	Molkind
12)	Whether the vehicle fitted with Anti-lock Braking System (ABS)?  a) If Yes, whether it is functioning or not? b) Whether trials regarding skid marks of ABS fitted vehicle have been carried out to estimate the speed of the vehicle	HA
13)	Whether vehicle modified by  a) Installing CNG/LPG Kit  b) Change of vehicle body	Hof any
14)	Condition of tyres-whether original or retreated?	08/3/1×5/