

2151  
4/12/2017

**DETAILED ACCIDENT REPORT (DAR)**  
**ANNEXURE 'A'**  
**MECHANICAL INSPECTION REPORT**  
(Submit separate Mechanical Report for each vehicle)

H.T.V. / M.G.V. / L.G.V.		
1	Case FIR No.	698/17
2	Under Section	u/s 279, 337
3	Police Station	Umred police station
4	Registration No. of the Vehicle	MH40/BG-2479
5	Make, Model Name, Colour & Type of Vehicle	Make - Ashok Leyland Model - 3118T Colour - yellow Type - Tipper
6	In case of HTV/MGV/LGV (a) Whether Lateral Under Run Protective Device (LUPD) & Rear Under Run Protective Device (RUPD) installed? (For vehicle weighing 3.5 ton or more) (b) Whether speed governor installed & functional or otherwise?	<del>fitting</del> N/A speed Gov. fitted & functional.
7	In case of commercial vehicle: a) Particulars of fitness b) Particulars of permit	4/18/2019 by Not provided At the time of inspection
8	Point of impact and damage -	front side.
9	Mechanical condition of the vehicle -	OK
10	Paint marks (if any) -	-
11	Condition of braking System i.e. working or not?	OK, working
12	Whether the vehicle fitted with Anti-lock Braking System (ABS)? a) If Yes, whether it is functioning or not? b) Whether trials regarding skid marks of ABS fitted vehicle have been carried out to estimate the speed of the vehicle	yes.
13	Whether vehicle modified by a) Installing CNG/LPG Kit b) Change of vehicle body	N/A
14	Condition of tyres-whether original or retreaded?	original
15	Whether horn was installed and functional?	electric horn functional
16	Whether the brake lights & other lights functional?	OK, functional
17	Condition of safety bags in the vehicle	N/A.

11633  
29/11/2017

18	Whether the vehicle properly maintained ?	ok
19	Whether the vehicle and faulty number plate?	NO
20	Whether the vehicle had tinted glasses?	NO
21	If the vehicle was educational institution bus, whether the vehicle was fitted with the doors that can be shut and whether the vehicle had a suitable inscription to indicate that they are in the duty of an educational institute, as per the guidelines laid down in MC Mehta v. Union of India, (1998) 1 SCC 676 and MC Mehta v. Union of India (1999) 1 SCC 413 ?	N/A
22	Details of damage on the vehicle - ① front Bumper pressed inside at the centre & right side	

*[Signature]*  
24/11/17

Mechanical Officer  
(Name & Stamp)

Neilesh D. Chaudhary

A.I.M.V. Dy. RTO Chandrapur

SHO  
(Name & Stamp)

Date : 24/11/17

**DETAILED ACCIDENT REPORT (DAR)**  
**ANNEXURE 'A'**  
**MECHANICAL INSPECTION REPORT**  
 (Submit separate Mechanical Report for each vehicle)

H.T.V. / M.G.V. / L.G.V.		
1	Case FIR No.	698/17
2	Under Section	U/S 279, 337
3	Police Station	unred police station
4	Registration No. of the Vehicle	MH33/A-5753
5	Make, Model Name, Colour & Type of Vehicle	make - Hyundai model - I20 colour - Red type - Lmv
6	In case of HTV/MGV/LGV (a) Whether Lateral Under Run Protective Device (LUPD) & Rear Under Run Protective Device (RUPD) installed? (For vehicle weighing 3.5 ton or more) (b) Whether speed governor installed & functional or otherwise?	N/A
7	In case of commercial vehicle: a) Particulars of fitness b) Particulars of permit	N/A
8	Point of impact and damage -	front & Rear
9	Mechanical condition of the vehicle -	m.v. found Not in Roadworthy condition.
10	Paint marks (if any) -	
11	Condition of braking System i.e. working or not?	m.v. found Not in Roadworthy condition
12	Whether the vehicle fitted with Anti-lock Braking System (ABS)? a) If Yes, whether it is functioning or not? b) Whether trials regarding skid marks of ABS fitted vehicle have been carried out to estimate the speed of the vehicle	N/A
13	Whether vehicle modified by a) Installing CNG/LPG Kit b) Change of vehicle body	N/A
14	Condition of tyres-whether original or retreaded ?	original
15	Whether horn was installed and functional ?	M.V. found not in
16	Whether the brake lights & other lights functional ?	Roadworthy condition
17	Condition of safety bags in the vehicle	oper. at the time of inspection (both front) Air Bag

11633

29/11/2017

18	Whether the vehicle properly maintained ?	—
19	Whether the vehicle and faulty number plate?	NO
20	Whether the vehicle had tinted glasses?	NO
21	If the vehicle was educational institution bus, whether the vehicle was fitted with the doors that can be shut and whether the vehicle had a suitable inscription to indicate that they are in the duty of an educational institute, as per the guidelines laid down in MC Mehta v. Union of India, (1998) 1 SCC 676 and MC Mehta v. Union of India (1999) 1 SCC 413 ?	N/A
22	Details of damage on the vehicle — ① front side total damaged ② radiator damaged, pressed inside bumper total damaged, engine damaged, battery damaged, front side total damaged. ③ windshield found broken ④ side panel total damaged. ⑤ Top Roof total damaged ⑥ front Head Light Assy. found missing ⑦ Dash board damaged. ⑧ All doors damaged ⑨ Rear side totally body pressed inside; Rear windshield found broken, tail lamp Assy. found missing. Rear Bumper damaged	

- ⑩ m.v. found not in Roadworthy & ss  
 condition hence opinion can not given.

Mechanical Officer  
 (Name & Stamp)

Milesh D. Chaudhari  
 A.I.M.V. Dy. Pro. Chandrapur  
 SHO  
 (Name & Stamp)

Date: 24/11/17