



20 पंलीस स्टेशन. समरुड  
2326/17  
29/12/17

19/12/17  
3.00 pm

DETAILED ACCIDENT REPORT (DAR)  
ANNEXURE 'A'  
MECHANICAL INSPECTION REPORT  
(Submit separate Mechanical Report for each vehicle)


H.T.V. / M.G.V. / L.G.V.		
1	Case FIR No.	740/17, *
2	Under Section	279, 304(अ) - 134/177, 184-
3	Police Station	Umred police station.
4	Registration No. of the Vehicle	MH34AF-6440
5	Make, Model Name, Colour & Type of Vehicle	Hero-Honda Splended Black-Gray - motor cycle.
6	In case of HTV/MGV/LGV (a) Whether Lateral Under Run Protective Device (LUPD) & Rear Under Run Protective Device (RUPD) installed? (For vehicle weighing 3.5 ton or more) (b) Whether speed governor installed & functional or otherwise?	} Not applicable NO
7	In case of commercial vehicle: a) Particulars of fitness b) Particulars of permit	} People verify
8	Point of impact and damage -	Front side
9	Mechanical condition of the vehicle -	Not in road worthy condition.
10	Paint marks (if any) -	At point of impact
11	Condition of braking System i.e. working or not?	Not in order
12	Whether the vehicle fitted with Anti-lock Braking System (ABS)? a) If Yes, whether it is functioning or not? b) Whether trials regarding skid marks of ABS fitted vehicle have been carried out to estimate the speed of the vehicle	} NO.
13	Whether vehicle modified by a) Installing CNG LPG Kit b) Change of vehicle body	} NO.
14	Condition of tyres-whether original or retreaded?	original
15	Whether horn was installed and functional?	Yes, Can't Tested
16	Whether the brake lights & other lights functional?	No, Can't Tested.
17	Condition of safety bags in the vehicle	Not applicable

PSI-ecost/17  
Gh  
21/12

जाबक क्र. 12403  
प्रादेशिक परिवहन कार्यालय  
नागपूर ग्रामिण. दिनांक 22/12/2017

18	Whether the vehicle properly maintained?	Yes.
19	Whether the vehicle and faulty number plate?	NO
20	Whether the vehicle had tinted glasses?	
21	If the vehicle was educational institution bus, whether the vehicle was fitted with the doors that can be shut and whether the vehicle had a suitable inscription to indicate that they are in the duty of an educational institute, as per the guidelines laid down in MC Mehta v. Union of India, (1998) 1 SCC 676 and MC Mehta v. Union of India (1999) 1 SCC 413?	NO
22	Details of damage on the vehicle - - front Alloy wheel broken - front suspension fork broken - Head light Assy broken - Handle damaged - front indicators broken motor cycle not in road worthy condition	

Date :

  
 Mechanical Officer  
 (Name & Stamp) 19/12/17  
 दत्तात्रय पुष्पाकर पांडेकर 3:00pm  
 स.पो.वा.नि.  
 प्रा.प.का.नागपूर(प्रा)  
 SHO  
 (Name & Stamp)

