

15)	Whether horn was installed and functional?	yes
16)	Whether the brake lights & other lights functional?	yes
17)	Condition of safety bags in the vehicle	NA
18)	Whether the vehicle properly maintained?	yes
19)	Whether the vehicle had faulty number plate?	NO
20)	Whether the vehicle had tinted glasses?	NA
21)	If the vehicle was educational institution bus, whether the vehicle had a suitable inscriptional to indicate that they are in the guidelines laid down in MC Mahra v. Union of India (1999)1SCC 413?	—
22)	Details of damage on the vehicle-	1) clutch lever broken 2) front body frame damaged 3) handle bent 4) front horn indicators dislocated 5) rear BHS body frame damage 6) chassis frame bent
23)	Opinion / Remark	opinion cannot give as road test is not possible due to heavy damage in motor vehicle.

Ch. no. 8179390
 Regd. no. MH40AL 8180

[Signature]
 19/6/18
 दिपक द. कोळ
 Mechanical Officer
 प्रा. व. का. नागपुर (ग्रामीण)

place: Mangar police chowki

Date: 19/6/2018 Time:
 Received by *[Signature]*
 PC/2018
 9/06/19C

SHO
 (Name & Stamp)

[Signature]
 किशोरकुमार ज. वैरागडे
 पोलीस उपनिरीक्षक
 फ़ोन. 9923795086