

82

पोलीस स्टेशन, उमरुड 35  
 आवक/जात्रक क्र 2281  
 दिनांक 22/12/17

HC 65 YAM  
 20/12

DETAILED ACCIDENT REPORT (DAR)  
 ANNEXURE 'A'  
 MECHANICAL INSPECTION REPORT  
 (Submit separate Mechanical Report for each vehicle)



H.T.V. / M.G.V. / L.G.V.

1	Case FIR No.	782117
2	Under Section	279, 337, 338, 304(A)
3	Police Station	IPCR/W 134177, 184177001
4	Registration No. of the Vehicle	Umred
5	Make, Model Name, Colour & Type of Vehicle	MH-34-AB-2207 Tata - Tipper - Gr. 3118C White - Boston red.
6	In case of H.T.V./M.G.V./L.G.V. (a) Whether Lateral Under Run Protective Device (LUPD) & Rear Under Run Protective Device (RUPD) installed? (For vehicle weighing 3.5 ton or more) (b) Whether speed governor installed & functional or otherwise?	a) RUPD & LUPD not fitted b) <del>Gov</del> Governor fitted
7	In case of commercial vehicle: a) Particulars of fitness b) Particulars of permit	I.O. To be ready
8	Point of impact and damage -	front
9	Mechanical condition of the vehicle -	Maintained
10	Paint marks (if any) -	NO
11	Condition of braking System i.e. working or not?	OK
12	Whether the vehicle fitted with Anti-lock Braking System (ABS)? a) If Yes, whether it is functioning or not? b) Whether trials regarding skid marks of ABS fitted vehicle have been carried out to estimate the speed of the vehicle	NO
13	Whether vehicle modified by a) Installing CNG/LPG Kit b) Change of vehicle body	NO
14	Condition of tyres-whether original or retreated ?	Right side tandem axle tyre tared, left side without
15	Whether horn was installed and functional ?	Pressure horn fitted functional
16	Whether the brake lights & other lights functional ?	Rear left tail lamp & indicator not working,
17	Condition of safety bags in the vehicle	N/A

जात्रक क्र 12083  
 प्रादेशिक परिवहन कार्यालय  
 नागपूर प्रांत, दिनांक 15/12/2017

76

18	Whether the vehicle properly maintained ?	Maintained
19	Whether the vehicle and faulty number plate?	NO
20	Whether the vehicle had tinted glasses?	NO
21	If the vehicle was educational institution bus, whether the vehicle was fitted with the doors that can be shut and whether the vehicle had a suitable inscription to indicate that they are in the duty of an educational institute, as per the guidelines laid down in MC Mehta v. Union of India, (1998) 1 SCC 676 and MC Mehta v. Union of India (1999) 1 SCC 413 ?	N/A
22	Details of damage on the vehicle - 1) front radiator grill bent 2)	



*Shamir*  
14.12.17

Mechanical Officer  
(Name & Stamp)  
 श्रीव अहमद चाऊस  
 स.पो.वा.नि.,  
 प्रा.प.कार्यालय, रामपुर (ग.)

SHO  
(Name & Stamp)

Date : 14.12.17

84

DETAILED ACCIDENT REPORT (DAR)  
ANNEXURE 'A'  
MECHANICAL INSPECTION REPORT  
(Submit separate Mechanical Report for each vehicle)



H.T.V. / M.G.V. / L.G.V. / M.C.W.G.		
1	Case FIR No.	T32/17
2	Under Section	279, 337, 338, 204(A)
3	Police Station	IPC, RW 124/17, 184: m road - Umerga.
4	Registration No. of the Vehicle	MH-34-AU-004-2
5	Make, Model Name, Colour & Type of Vehicle	Hero - Passion Pro Black - Red
6	In case of HTV/MGV/LGV (a) Whether Lateral Under Run Protective Device (LUPD) & Rear Under Run Protective Device (RUPD) installed? (For vehicle weighing 3.5 ton or more) (b) Whether speed governor installed & functional or otherwise?	N/A
7	In case of commercial vehicle: a) Particulars of fitness b) Particulars of permit	N/A
8	Point of impact and damage -	front
9	Mechanical condition of the vehicle -	m.v. not road worthiness condition
10	Paint marks (if any) -	NO
11	Condition of braking System i.e. working or not?	m.v. not road tested, hence opinion can't be expressed
12	Whether the vehicle fitted with Anti-lock Braking System (ABS)? a) If Yes, whether it is functioning or not? b) Whether trials regarding skid marks of ABS fitted vehicle have been carried out to estimate the speed of the vehicle	NO
13	Whether vehicle modified by a) Installing CNG/LPG Kit b) Change of vehicle body	NO
14	Condition of tyres-whether original or retreated ?	original
15	Whether horn was installed and functional ?	Installed but could not be tested
16	Whether the brake lights & other lights functional ?	Head light assembly broken
17	Condition of safety bags in the vehicle	N/A

जांचक 12083  
प्रादेशिक परिवहन कार्यालय  
नागपूर ग्रामिण विभाग 15/12/2017

58

18	Whether the vehicle properly maintained ?	I.O. To be verified
19	Whether the vehicle and faulty number plate?	NO
20	Whether the vehicle had tinted glasses?	NO
21	If the vehicle was educational institution bus, whether the vehicle was fitted with the doors that can be shut and whether the vehicle had a suitable inscription to indicate that they are in the duty of an educational institute, as per the guidelines laid down in MC Mehta v. Union of India, (1998) 1 SCC 676 and MC Mehta v. Union of India (1999) 1 SCC 413 ?	N/A
22	Details of damage on the vehicle -	

- 1) Head light assembly broken
- 2) front shock absorber band
- 3) front mudguard broken.
- 4) Both side side panel broken
- 5) tail Lamp broken
- 6) chain cover broken.
- 7) motor cycle chassis frame bend.
- 8) Leg-guard broken.
- 9) Speedometer broken



*Sharma*  
14.12.17

Mechanical **वहीद अहमद चाऊस**  
(Name & Stamp)

SHO **स.मो.वा.नि.,  
प्रा.प.कार्यालय, नगपुर (ग्रा.)**  
(Name & Stamp)

Date : 14.12.17