


ANNEXURE 'A'

MECHANICAL INSPECTION REPORT (DAR)

071

1)	Case FIR No.	358/18
2)	Under Section	304(A). 279, 387, 388. 184
3)	Police Station	P. S. Ramtek
4)	Registration No. of the Vehicle	MH40 AL- 8180
5)	Make, Model Name, Colour & Type of Vehicle	Honda/ Aviator/ Black / 2w.
6)	In case of HTV/ MGVL/GV (a) Whether Lateral Under Run Protective Device (LUPD) & Rear Under Run Protective Device (RUPD) installed? (For vehicle weighing 3.5 ton or more) (b) Whether speed governor installed & functional or otherwise?	NA
7)	In case of commercial vehicle : (a) Particulars of fitness (b) Particulars of permit	NA
8)	Point of impact and damage-	Front side
9)	Mechanical condition of the vehicle-	Not in road worthy condition
10)	Paint marks (if any-)	—
11)	Condition of braking System i.e. working or not?	Not in condition of testing
12)	Whether the vehicle fitted with Anti-lock Braking System (ABS)? a) If Yes, whether it is functioning or not? b) Whether trials regarding skid marks of ABS fitted vehicle have been carried out to estimate the speed of the vehicle	NA
13)	Whether vehicle modified by a) Installing CNG/LPG Kit b) Change of vehicle body	Not any.
14)	Condition of tyres-whether original or retreated?	original


 किशोरकुमार ज. वैयगडे
 पोलीस उपनिरीक्षक
 मो. 9923795086